Sector	QPCode	Job Role Name	NSQF Level	Equipment Name	Minimum number of Equipment required (per batch of 30 trainees)	Unit Type	Is this a mandatory Equipment to be available at the Training Center (Yes/No)	Dimension/Specification/Des cription of the Equipment/ ANY OTHER REMARK
Mining	MIN/Q0416	Mine Electrician	4	Reflective Jacket	15	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Helmet	15	Set	Yes	Practical Training can be done at underround mine
Mining	MIN/Q0416	Mine Electrician	4	Gum Boots	15	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Dust Mask	1	Set per Trainee	Yes	50 meter
Mining	MIN/Q0416	Mine Electrician	4	Ear Plug	1	Set per Trainee	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Fire Extinguisher Cylinders	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	First Aid Box	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Fire Fighting Charts	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	First Aid Charts	1	Set	Yes	_
Mining	MIN/Q0416	Mine Electrician	4	Hand Gloves	15	Pair	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Connection Bushing Terminal	1	Set	Yes	

Mining	MIN/Q0416	Mine Electrician	4	Bus Bar	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Mcb	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	China Clay Oil Filled Insulator	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Board Switch	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Power Supply Monitor Panel Board	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Earthing Equipment Set	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Solding Iron And Consumables	5	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Clamp Meter	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Digital Multi Meter	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Switchgear	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Screw Driver Set	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Phase Tester	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Combination Pliers	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Nose Pliers	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Spanner Set	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Adjustable Wrench	2	Set	Yes	

Mining	MIN/Q0416	Mine Electrician	4	Pipe Wrench	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Measuring Tape	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Hack Saw	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Hammer	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Chisel	2	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Files Set	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Wood Saw	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Portable Drill Machine	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Bench-Vice & Line- Vice	1	Set	Yes	Can be on hired system for practical training
Mining	MIN/Q0416	Mine Electrician	4	Modal of sub- station	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Eletric Grinder	1	Set	Yes	Complete System
Mining	MIN/Q0416	Mine Electrician	4	Single phase transformer 2 KVA	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	3 phase transformer oil filled 10 KVA	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	3 phase squirrel cage Induction motors 5HP	1	Set	Yes	
Mining	MIN/Q0416	Mine Electrician	4	Modal of continuity of circuits	1	Set	Yes	